THE EMB-120 BRASILIA IN SLD CONDITIONS & EMBRAER FLIGHT OPERATIONS SUPPORT FOR WINTER OPS

Juarez Machado

October 2011



Commercial Jets

SERVICES AND SUPPORT

Background

Background Information

- ATR-72 accident at Roselawn, in October 1994, which resulted in an inflight loss of control and subsequent dive until collision with the ground.
- The weather at the time of the accident involved atmospheric conditions outside of the FAA part 25 Appendix C, and involved freezing rain and freezing drizzle.
- At that time, no aircraft was required to demonstrate the capability of flying in severe icing conditions (SLD).
- Ice is a surprising phenomena -> loss of a turboprop at Los Menucos (Argentina) on May 2011, possibly involving severe icing, stall and loss of control.
- Embraer was required by certification authorities to assess the roll characteristics of the EMB-120 in SLD conditions.



SERVICES AND SUPPORT



FLIGHT TEST PREPARATION

BEFORE CARRYING OUT FLIGHT TESTS

- Wind tunnel tests with artificial ice shapes to measure the effect on the aileron hinge moment.
- 1 and ½ inch have been evaluated for various aileron displacements.
- Hinge moment, loss of lift, drag increase, and rolling moments were introduced in the simulator model and flown.
- Results: after **successful** simulator flights, it was decided that a 1 and ½ inch wooden quarter molding should be positioned at the end of the last boot inflatable tube and proceed to real flights.



SERVICES AND SUPPORT



FLIGHT TEST PREPARATION



SERVICES AND SUPPORT

THIS INFORMATION IS EMBRAER PROPERTY AND CANNOT BE USED OR REPRODUCED WITHOUT WRITTEN AUTHORIZATION

Commercial Jets

FLIGHT TEST WITH ARTIFICIAL ICE

TO TAKEOFF SAFELY (SAFETY FIRST, NO SECRET)

- High speed taxi and operation of the jettison device.
- Flight with a molding covering 1/3 of the aileron span, first 1/2 inch molding, then 1 inch molding on both wings.
- Flight with the molding covering 2/3 of the aileron span on both wings.
- Flight with the molding covering full aileron span length. Artificial ice shapes released asymmetrically in flight.

FLIGHT TEST RESULTS

- The aircraft was considered fully controllable.
- (Despite of) Simulated ice shape much more critical than a real SLD.
- (Despite of) Highly conservative test condition.



FLIGHT TEST WITH ARTIFICIAL ICE



SERVICES AND SUPPORT



Purpose

- ...to determine the shape of the ice accumulated during freezing rain/freezing drizzle.
- ...to determine the visual cues to allow pilots to recognize when they are flying in SLD conditions.



SERVICES AND SUPPORT



The Icing Tanker and Chase Plane (cameras everywhere)

- A USAF KC-135 with boom-mounted water nozzle array.
- Capable of producing an icing "cloud" with the correct droplet size and water content.
- A Learjet was used as chase plane, with proper equipment to calibrate the water spray.





SERVICES AND SUPPORT





SERVICES AND SUPPORT



The Emb-120 Aircraft

- s/n 120.038, normal deicing boots with no surface treatment, very representative of the fleet.
- Total test time: 5,7 hours
- Airspeed: 160 and 175 kt
- Temperature: -1 < t < +5 deg C
- MVD: 40 **µ** and 170 **µ**
- LWC: 0,5 g/m³ and 0,65 g/m³



SERVICES AND SUPPORT





SERVICES AND SUPPORT



Flight Test Results

- Wing and engine air inlet boots, propeller, windshield and pitotstatic tubes (elec anti-ice) exposed to SLD. All operated normally.
- Systems activated according to the AFM procedures.
- Flying qualities, handling and controllability remained unchanged.
- Ice indicator close to the pilot's side window is not effective.
- Ice on the windshield and propeller blades did not reveal any SLD cue.
- SLD ice on the wing and spinner revealed different accumulation patterns from normal icing, and were declared AFM appropriate visual cues.



SERVICES AND SUPPORT



40 μ SPRAY ON THE SPINNER



Normal ice spray on the spinner shows ice accumulation concentrated on forward half.

170 μ SPRAY ON THE SPINNER



SERVICES AND SUPPORT



40 μ SPRAY ON THE WING

These photos show normal icing in which ice begins forming on the protected area, where the inflation tubes are provided.



170 μ SPRAY ON THE WING

SLD ice spray on the wing shows ice accumulating on the de-icer aft of the last inflatable rib.



SERVICES AND SUPPORT





SERVICES AND SUPPORT



PROCEDURES RESULTING FROM THE TESTS OR REQUIRED BY CERTIFICATION

- Turn boots immediately after recognizing icing conditions
- Turn AP off in icing (later authorized if installing the low speed alarm)
- AP off when flying SLD conditions
- Specific information regarding AP disengage, flaps operation, speeds to use etc
- Extensive revision to the AFM and issue of a special OPERATIONAL BULLETIN
- * Distribution of a dedicated video covering all aspects regarding winter ops (Embraer Flt Ops initiative)!

ADDITIONAL AIRCRAFT MODIFICATIONS:

- Installation of the LOW SPEED ALARM for icing conditions (IAS < 160 kt)
- Installation of the ice detection system.
- Operation with only the fastest boot inflation cycle
- ... no boots size change





SERVICES AND SUPPORT





SERVICES AND SUPPORT

THIS INFORMATION IS EMBRAER PROPERTY AND CANNOT BE USED OR REPRODUCED WITHOUT WRITTEN AUTHORIZATION

EMBRAER Commercial Jets

- **1. EARLY INVOLVEMENT**
- 2. GLOBAL AWARENESS
- **3. CONTINUOUS CARE WITH ALL FLEETS**
- 4. KEEP FLYING
- **5. SHARE KNOWLEDGE**



SERVICES AND SUPPORT



EARLY INVOLVEMENT

- Presentations to design engineers of ice-related lessons-learned
- Specific inputs during new aircraft development and follow-up of system design
- Test proposal discussion
- Fight/ground tests personnel participation: cold soak (Eglin Alaska Russia), in-flight real icing tests
- Sharing of flight/ground test results.



SERVICES AND SUPPORT



GLOBAL AWARENESS

- PARTICIPATION IN SAE G-12
 - 2 engineers continuous follow-up
- WINTER OPS CONGRESSES CANADA, EUROPE, USA
 - 6 + engineers at the last Chicago Congress
- SAFETY ISSUES: Keep tracking of ice-related incidents and accident reports.
- PUBLICATIONS (FAA, EASA, TCAG, AEA, SAE): ARPs, SAFOs, ACs, ADs, SIBs, ____, ____ etc



SERVICES AND SUPPORT



CONTINUOUS CARE OF ALL FLEETS

- How does a new issue affect ALL Embraer aircraft?
- How is the fleet performing with regard to new technologies?
- How is the current airframe performing with regard to existing technologies?
- What can be done to solve a new issue? Will the airlines get it?



SERVICES AND SUPPORT



KEEP FLYING

- Continuous contact with flight crews.
- Continuous research in Airline Flight Standards.
- Go to ice, wherever it is.





SERVICES AND SUPPORT



SHARE KNOWLEDGE/EXPERIENCE

- FOR AFM/CERTIFICATION PURPOSES
- FOR STANDARD PROCEDURES AND OPERATIONS MANUAIS
- FOR MAINTENANCE PROCEDURES
- FOR CONSISTENCY OF INFORMATION BETWEEN EMBRAER
 INTERNAL AREAS
- FOR DESIGN SUPPORT
- FOR SAFETY PURPOSES
- FOR PRODUCING SPECIFIC TRAINING MATERIAL







Operational Videos EMB 120

Operational Video Download



EMB 120



VD 120001 Operation In Icing Conditions Operat 1 [23900 kb] Part 2 [21100 kb] Part 3 [30200 kb] Part 4 [29200 kb]



VD 120003 - EMB-120 Upset Recovery Part 1 [23900 kb] Part 2 [21100 kb] Part 3 [30200 kb] Part 4 [29200 kb]



VD 120004 - EMB-120 Recuperação de Upset Part 1 [27500 kb] Part 2 [20800 kb] Part 3 [19100 kb] Part 4 [20300 kb]



VD 120005 - EMB-120 Evacuações de Emergência O Part 1 [25600 kb] O Part 2 [21000 kb] O Part 3 [18600 kb] O Part 4 [27300 kb]



SERVICES AND SUPPORT



Operational Videos

Operational Video Download

ERJ 145





OV 145001 (MAY/2001) New Gust Lock System Ownload [7420 kb](00:03:23)



VD 145001 (MAY/2001) Jet Transition Part 1 [17700 kb](00:10:01) Part 2 [14700 kb](00:09:17) Part 3 [16500 kb](00:09:34) Part 4 [16100 kb](00:09:31) Part 5 [10500 kb](00:07:14)



OV 145002 (JAN/2001) Pitch Trim Operation Operation (17100 kb)(00:07:09)



VD 145002 (OCT/2001) Regional Jets Operation In Icing Conditions Part 1 [19300 kb](00:11:32) Part 2 [20600 kb](00:011:16) Part 3 [15600 kb](00:08:24) Part 4 [12300 kb](00:06:35) Part 5 [24200 kb](00:12:45)



OV 145003 (NOV/2001) Pressurization Manual Mode Opwnload [21100 kb](00:11:16)



VD 145003 (MAY/2002) Head-up Guidance System Part 1 [18100 kb](00:09:38)

SERVICES AND SUPPORT



Operational Videos EMBRAER 170/175/190/195

Operational Video Download

EMBRAER 170/175/190/195





OV 170001 - REV 1 (OCT/2005) EMBRAER 170 Operation In Icing Conditions Opert 1 [23900 kb](00:13:14) Part 2 [21100 kb](00:16:23) Part 3 [30200 kb](00:16:09)



OV 170002 - REV1 (AUG/2006) EMBRAER 170 / 190 Upset Recovery Part 1 [20452 kb](00:10:25) Part 2 [49146 kb](00:15:41) Part 3 [31789 kb](00:12:53)



OV 170003 (DEC/2004) Fligh Path Vector O Part 1 [18900 kb](00:10:06) O Part 2 [24700 kb](00:12:03)



OV 170004 - REV 1 (JUN/2005) Vertical Navigation VNAV O Part 1 [20700 kb](00:11:44) O Part 2 [19700 kb](00:11:50) O Part 3 [20800 kb](00:11:47)



OV 170005 - REV 1 (MAR/2009) EMBRAER 170 / 190 Power Up and Power Down Procedures C Download [15297 kb](00:07:34)



OV 170006 - REV 2 (MAR/2009) EMBRAER 170 / 190 Doors Operation Operation

SERVICES AND SUPPORT



Operational Video Download



OV-500/001 Single Pilot Operation O Part 1 [153792 kb] O Part 2 [251464 kb]



Phenom 100/300

OV-500/002 Adverse Weather Operation O Part 1 [15345 kb] O Part 2 [35495 kb]



OV-500/003 Fluid Application Part 1 [10820 kb] Part 2 [4513 kb] Part 3 [6090 kb] Part 4 [6991 kb] Part 5 [5404 kb] Part 6 [4016 kb]



OV-500/004 Jet Transition Part 1 [47814 kb] Part 2 [37188 kb]



OV-500005 Runway Overrun Prevention Part 1 [15031 kb](00:04:58) Part 2 [15426 kb](00:04:25)



OV-500/006 Emergency Braking Technique Part 1 [37730 kb](00:05:26) Part 2 [18498 kb](00:02:29)

SERVICES AND SUPPORT

THIS INFORMATION IS EMBRAER PROPERTY AND CANNOT BE USED OR REPRODUCED WITHOUT WRITTEN AUTHORIZATION

Commercial Jets

THANK YOU

www.embraer.com.br

opereng@embraer.com.br

jucamachado@embraer.com.br

SERVICES AND SUPPORT

