EXECUTIVE SUMMARY – 433rd UKFSC SIE MEETING – 8 NOVEMBER 2016

- 1. High Court Judgments preventing disclosure of safety information. (4.2)
- 2. **RJ100** stick shaker and stick pusher activate shortly after take-off, requiring second pilot to assist with maintaining pitch attitude. (5.1)
- 3. Narrow escape for ground personnel closing hangar door falling object. (5.2)
- 4. Control restriction: incorrectly stowed EFB fouled collective pitch lever during night training flight. (5.5)
- 5. Vibration from undiagnosed engine surge (no captions) led to RTO. Sub-optimal training simulator not capable of replicating noise/vibration symptoms. (5.5)
- 6. Crews were not always complying with the requirement to maintain at least 500fpm when making cleared altitude changes, or to advise ATC if unable. (5.6)
- 7. Potential for confusion due to delayed UK introduction of PANS-ATM changes to SID/STAR phraseology. (5.6)
- 8. Runway incursion after deportee escaped from escort at aircraft steps and went 'on the run' and then onto the runway... Recaptured, deported. (5.8)
- 9. ECAM message indicated shock absorber fault during pax disembarkation; nose oleo was found to be 5-10 mm from full extension. CG 45-47% MAC, tipping point 57% MAC. (5.10)
- 10. Wake vortex encounter after levelling at FL310; AP disengaged and aircraft rolled rapidly, causing some minor injuries. (5.11)
- 11. On-airport SAR helicopter drone encounter (5.12)
- 12. Inadvertent helicopter flight: pilot accidentally caught collective pitch lever during checks. Aircraft landed immediately, no damage. (5.13)
- 13. FDM survey of US business operators showed 17% do not conduct full and free control checks. (5.15)
- 14. B747 hard landing, possible fatigue and pilot monitoring issues. (5.17)
- 15. A330 hit by loose baggage cart. Baggage being towed too fast, uneven ground caused the rear cart to separate, rear safety latch not engaged and in poor condition. (5.17)

Dai Whittingham Chief Executive 5 December 2016