EXECUTIVE SUMMARY - 406TH UKFSC SIE MEETING 9 MAY 2012

- 1. B737 tailstrike incorrect data entry, 10% error on gross weight, failure to cross-check. (5.1)
- 2. A300-600. Near-fatal accident during pushback. Aircraft struck the tug, narrowly missing the tug driver. SOPS amended. (5.1)
- 3. AAIB investigation into A330 evacuation at LGW will look at decision making and evacuation process with a view to developing guidance for flight crews. (5.1)
- 4. A320 autobraking incident at LHR. (5.1)
- 5. Apps for smartphones being used operationally despite lack of formal clearances. Electronic documentation need the same level of control as that used with EFBs. (5.4)
- 6. Single aerodrome RVP unavailable during emergency due to positioning of safety cordon. (5.4)
- 7. Confusion being generated by incorrect use of phonetics in callsigns. A runway incursion resulted from use of a 'Delta' suffix and the presence of a Delta crew. (5.4)
- 8. Wake turbulence encounter. Preceding ac descended as cleared in oceanic airspace. Procedural separation (8 miles) not infringed, but still caused upset. (5.9)
- 9. B757 engine shutdown, fatigue failure of spinner assembly. (5.9)
- 10. Significant discrepancies between individual aircraft load sheets on delivery of new aircraft. (5.12)

Dai Whittingham Chief Executive 25 May 2012