

Local Runway Safety Team Action Log 12th May 2010

Attendees: J Barkley ACM, Dave Charman ASSTM, Phil Rowsell RFFS, Glenn Bradley EZY, Janet Gilroy ACSM, Ross MacDonald NATS, Nigel Hollett Menzies, Richard Munt Swissport, Ron Fitt SVS, Police, Ian Middleton FlyBe, Rich Jones UK Flight Safety Committee, Dave Perry Airdat, Derek Carlton GAL, Keith Burridge AACM, Al Pease Thomson
Apologies: Tim Price BA, Paul Wiggins BA, Andy Taylor NATS, Justina Beeken Police, Liam O'Reilly, Trevor Speed Police, Kevin Wilkins AOM, Simon Heath DSM,

Shared material reviewed at this meeting;

Low Visibility Presentation

LRST key learning points;

London **Gatwick Airport**

No	Issue	Action	Resp	COMPLETION DATE		Comments
				Planned	Actual	
1	Charlie Hold	Measures to be introduced to reduce the risk of a vehicle induced runway incursion at C1	JB/DC	April 2010		Agreed (short and long term options). Short term; installing red reflective studs to east of stop bar – (Action JB) to obtain SRG buy in by next LRST meeting Long term solution; remove concrete south of this line and grass as part of Main RWY rehabilitation project – to be included in Runway resurfacing project brief. (Action JB)
2	Free ranging	Safety Survey – Northern Runway Operations during Main Runway maintenance <ul style="list-style-type: none"> Input requested from Airlines/Ops 	AT	June 2010		Easyjet have agreed to supply input with Glenn Bradley to supply any relevant details from other airports Ian Middleton (IM) to be included in survey.

London Gatwick Airport

3	Runway stopbars	<ul style="list-style-type: none">Review of vehicle crossing runway stopbars required in line with CAP 493Workshop to be held between NATS and GAL.Review new Heathrow ‘full length’ inspection process as part of this work	AT and JB	July 10 July 10 June 10		<p>Date to be arranged once AGL control upgrade complete – Awaiting response from ATG – AT to confirm dates with Kevin O’Leary for upgrade.</p> <p>Vehicle Protocol workshop to include the airfield operations multi vehicle inspections. Adoption of sterile cockpit technique in vehicles when on RWY – JB to arrange KW/AT to contact LHR re trial feedback.</p>
4	Airfield Charts	Some items identified by NATS in the AIP as being incorrect; forwarded to GAL Compliance Team to address.	JB / JG	April 10	Comp Comp Comp	<p>AIP has been reviewed and amendments made. JB to check agreement with chart providers.</p> <p>BJ to send details of changes to appear in AIP to LRST group.</p> <p>JB to update AIP re Dash 8 pick up parking. DC to issue NOTAM re above</p> <p>BJ to check ‘J7’ position is correct in AIP. JB checked latest AIP and all is correct IM to check charts used by Flybe ref ‘J7’.</p>

London Gatwick Airport

5	Manoeuvring Area driving map	Develop map for airside driving	JB	April 10	<div> <div>1. Comp</div> <div>2. Comp</div> <div>3. Comp</div> <div>4. In prog</div> <div>5. Comp</div> <div>6. Comp</div> <div>7. In prog</div> <div>8. In prog</div> <div>9. Not req</div> <div>10. In prog</div> <div>11. On going</div> <div>12. Comp</div> </div>	<p>Draft reviewed – comments remain;</p> <ol style="list-style-type: none"> label AS not Alpha South put expiry date on chart show RVPs include 'lost procedure Resize map as large as possible and simplify Show that ATC approval required on Northern RWY when in use a taxiway. Include "U" colour old "F" rwy exit red. 2 maps; Main RWY and Northern. Add 'apron area' and make stand numbers clearer Leave block and grass area numbers Classified as Manoeuvring Area Map Not required in apron roads and stand access only vehicles. Findnet/ Website. Update for next mtg. to be issued to LRST (with actions list and agenda) for comment
---	------------------------------	---------------------------------	----	----------	--	--

London Gatwick Airport

6	CGA markings	Burnt Line to be introduced	DC	May 10		Line will be shaped to join up CAT 1 holds with CGA line – to avoid vehicle being at edge of TWY outside of line, but inside Holding point. CGA line at RWY access road to be at 90m from RWY centreline
		Line to be surveyed for exact position before being implemented. Test required on A-SMGCS RIMCAS alerting	DC	May 10		The Subject is included in Runway resurfacing project brief.
7	Amalgamated actions list from other airports	Priority list drawn up on amalgamated actions list from other airports for discussion at next meetings subject to available time (until list completed)	ALL	Ongoing		
		<ul style="list-style-type: none">• JB to share other airports action lists with actions from meeting	JB	May 2010		Continues to be insufficient time to review this action during meetings - List to be mailed to LRST group and review away from meeting and items that should be actioned here to be e mailed to JB/AT . Compliant with CAP 168
11	Vehicle Transponders	Fit transponder to Ops 8 vehicle (SH)	SH / NATS	April 10		AT to check with NATS and CAA

London **Gatwick Airport**

12	Runway Incursion Comms	Produce a 1 page summary of 2009 runway incursion performance.	JB / AT	Jan 10	Comp	Produce overlay of incursions since 2007 as overview for Feb 2010 LRST meeting to decide HOTSPOT map required No current HOTSPOT issue at Gatwick Details shared re latest incursion's results to be shared at next meeting.
13	LVP review/table top ex	2 hour meeting to be arranged to review all part of LVP procedures and ensure ongoing consistency between NATS and GAL departments. RWY safety/avoidance of incursions in LSA and critical areas to be specific focus	JB / AT/RM	April 10	Comp	Meeting arranged for 26 Feb 2010 – outcome to be briefed at LRST meeting by Ross MacDonald
14	Supply dates of walking inspections of RWYs and adjacent TWYs to LRST addressees so that they can take part	Runway Walking Inspections which are:- April 22nd and November 11th 2010 .	DC	May 2010	Comp	